



CONNECTORS

- RF I/P - SMA (F)
- FWD MON(- SMA (F)
- REV MON(- SMA (F)
- RF O/P - N-TYPE (F)
- DC/CONTROL - 7W2 PLUG/
- FAN POWER - SMP-04V-NC

A - TAP M4 THRU (12 OFF)



A1	0V (GND)
A2	+50V
1	NC
2	NC
3	OVERTEMP ALARM
4	TTL - HIGH = OFF
5	-8V INPUT